


Rose Hill Coalition

Rose Paper: VDOT Observations

Opposition to Nomination CPN22-LE-001

VDOT Observations

100 positive responses



- The drainage easements were not properly platted or deeded when created, thus the outfalls were not transferred to a subsequent maintenance entity
- The outfalls were constructed with intent to transfer responsibility to VDOT, but the process was not completed
- There is an entity assigned with responsibility to maintain the outfalls, but that entity was unaware of the obligation
- There is an entity assigned with responsibility to maintain the outfalls, but that entity lacks sufficient funds to adequately perform the maintenance
- There are insufficient records to determine the responsible party
- Not applicable, there is not much of a problem with unmaintained outfalls in this county